









TECHNICAL INFORMATION

SUBJECT: Blunt and Cutter support on ECHO HC-156, HC-1501, HCR-1501, DH221, HCR-165ES, HCR-185ES, shindaiwa DH165ST and DH185ST

Number: Y2017-621 (1/2)
Issued: Mar. 31, 2017

Blunt and cutter support are supplied separately for maintenance.		
HC-156	Serial Number 37005200 and before	Serial Number 37005201 and after
Blunt	 <p>Not supplied separately</p> <p>Not supplied separately</p> <p>P021-047780</p>	 <p>X431-000200</p> <p>X425-000960</p>
Cutter support		Nil
Cutter support assembly		Nil
Blunt X431-000200 can be used on the unit before this change. Cutter support X425-000890 can be used on the unit before this change.		
HC-1501	Serial Number 37018570 and before	Serial Number 37018571 and after
HCR-1501	Serial Number 37005260 and before	Serial Number 37005261 and after
DH221	Serial Number 37002900 and before	Serial Number 37002901 and after
Blunt	 <p>Not supplied separately</p> <p>Not supplied separately</p> <p>P021-045630</p>	 <p>X431-000200</p> <p>X425-000890</p>
Cutter support		Nil
Cutter support assembly		Nil
Blunt X431-000200 can be used on the unit before this change. Cutter support X425-000890 can be used on the unit before this change.		

TECHNICAL INFORMATION Number: Y2017-621 (2/2)

HCR-165ES	Serial number 37013482 and before	Serial number 37013483 and after
DH165ST	Serial number 37001920 and before	Serial number 37001921 and after
<p>Blunt Cutter support assembly</p> <p>Cutter support</p> <p>Cutter assembly</p>	 <p>Not supplied separately</p> <p>P021-049620</p> <p>Not supplied separately</p> <p>X041-000491</p>	 <p>X431-000210</p> <p>Nil</p> <p>X425-000900</p> <p>P100-002710</p>
<p>Blunt X431-000210 can be used on the unit before this change. Cutter support X425-000900 can be used on the unit before this change. Cutter assembly X041-000491 can be replaced with P100-002710.</p>		
HCR-185ES	Serial number 37007173 and before	Serial number 37007174 and after
DH185ST	Serial number 37001828 and before	Serial number 37001829 and after
<p>Blunt Cutter support assembly</p> <p>Cutter support</p> <p>Cutter assembly</p>	 <p>Not supplied separately</p> <p>P021-049630</p> <p>Not supplied separately</p> <p>X041-000501</p>	 <p>X431-000210</p> <p>Nil</p> <p>X425-000910</p> <p>P100-002720</p>
<p>Blunt X431-000210 can be used on the unit before this change. Cutter support X425-000910 can be used on the unit before this change. Cutter assembly X041-000501 can be replaced with P100-002720.</p>		