

TECHNICAL INFORMATION



SUBJECT: Serial Number label and ignition coil on
ECHO CS-2511TES, shindaiwa 251TCs and 251Ts

Number: Y2018-660
Issued: Nov. 30, 2018
Revised: Feb. 28, 2019

| | | |
|---|--|---|
| Changed ignition coil for more stable idle speed. | | |
| CS-2511TES(33) | Serial Number 33002510 and before | Serial Number 33002511 and after |
| CS-2511TES(37) | Serial Number 37063060 and before | Serial Number 37063061 and after |
| 251TCs(37) | Serial Number 37010000 and before | Serial Number 37010001 and after |
| 251Ts(37) | Serial Number 37008940 and before | Serial Number 37008941 and after |
| Serial Number label | <p>Sticker type</p> <p>Model name</p> | <p>Laser etched type</p> <p>Model name</p> <p>Added mark "(P)"</p> |
| Ignition coil | <p>P021-050160</p> <p>Mark: A</p> | <p>Parts on production</p> <p>or</p> <p>Mark: P</p> <p>Mark: P [1]</p> <p>Spare parts only</p> <p>P100-006570</p> <p>Mark: P [1]</p> |
| The parts before change and after change are not interchangeable independently. | | |

NOTE: When using changed ignition coil, refer to SERVICE DATA.
For carburetor change, refer to TECHNICAL INFORMATION No.Y2018-659.

--- Ignition coil with mark 'P' and mark 'P[1]' ---

Change to Carburetor adjustment mode

Start engine without brake activated and do not touch throttle lever.

- | | |
|--|----------|
| 1) Engine warm-up with Fast idle (6,000 - 10,000* r/min) | 120 sec. |
|--|----------|

* If it is not, adjust the fast idle speed by turning H mixture needle.

CAUTION: Chain starts to rotate during engine warm-up with Fast idle.

NOTE: Do not stop engine during carburetor adjustment. If engine is stopped, restart this procedure from the beginning.