

TECHNICAL INFORMATION







SUBJECT: Auto-oiler puller and Auto-oiler installer

Number: Y2019-665
Issued: Apr. 30, 2019

Introduced slim auto-oiler tool.

After this change, the auto-oiler of ECHO DCS-1600 can be removed and installed with these tools.

	Before change	After change
Auto-oiler puller	 <p>Y089-000130</p>	 <p>Y089-000131</p>
Auto-oiler installer	 <p>91073</p>	 <p>91073A</p>
<p>Auto-oiler puller Y089-000130 can be replaced with Y089-000131. Auto-oiler installer 91073 can be replaced with 91073A.</p>		

NOTE: For removing and installing auto-oiler, refer to SERVICE MANUAL No.400-01A.