









TECHNICAL INFORMATION

SUBJECT: Piston kit on ECHO PB-8010

Number: Y2020-691
Issued: Oct. 30, 2020
Revised: Nov. 30, 2020

Changed piston ring and piston to improve performance.

PB-8010 (38)	Serial Number 38010000 and before	Serial Number 38010001 and after
Piston ring	 <p>A101-000750 : 2 pcs</p>	 <p>A101-000820 : 2 pcs</p>
Piston	 <p>Not supplied separately</p>	 <p>Not supplied separately</p>
Piston kit	<p>P100-008020</p>  <p>View A</p>  <p>Cut view C</p>	<p>P100-008021</p>  <p>View B</p> <p>Mark "T"</p>  <p>Cut view C</p>
<p>Piston ring A101-000750 is superseded by piston kit P100-008021. Piston kit P100-008020 can be replaced with P100-008021.</p>		